

Warren Vintage  
Trucks 1620 S.  
Johnson St.  
Amarillo, TX 79102  
(806)374-3056

Exclusive manufacturer of Diamond T Truck rubber part replacements by injection molding of polyurethane elastomers. Products are guaranteed to customer satisfaction. Any unused parts purchased may be returned for a full refund within 30 days of original purchase.

The following pages contain Parts Lists (Pages 1-5) and an Order Form (Page 6).

Please print the Order Form and neatly PRINT your Part Number, along with other information, and follow the ordering instructions and mailing information located on the Order Form. Prices listed are subject to increase based on material and labor costs. As such, the prices listed are to be considered estimates. If you have questions, and to obtain total and shipping costs, please call us at (806)374-3056.

## Table Of Contents

<b>Running Board Strips.....</b>	<b>Page 1</b>
<b>Strips With Flat Bottoms. ....</b>	<b>Page 1</b>
<b>80 Expresses (old Style) Pickup ..</b>	<b>Page 1</b>
<b>201 And Other Pickups.....</b>	<b>Pages 1, 2</b>
<b>210, 211, and 212.....</b>	<b>Page 2</b>
<b>220 With JXB Hercules.....</b>	<b>Page 2</b>
<b>306 (Farm Trucks).....</b>	<b>Pages 2, 3</b>
<b>Larger Trucks. ....</b>	<b>Page 3</b>
<b>Most Any Diamond T.....</b>	<b>Pages 3, 4</b>
<b>Motor Mounts....</b>	<b>Page 4</b>
<b>702.....</b>	<b>Page 4</b>
<b>Accessories. ....</b>	<b>Pages 4, 5</b>
<b>Floor Mats. ....</b>	<b>Page 5</b>
<b>Order Form.....</b>	<b>Page 6</b>

Exclusive manufacturer of Diamond T Truck rubber part replacements by injection molding of polyurethane elastomers. Products are guaranteed to customer satisfaction. Any unused parts purchased may be returned for a full refund within 30 days of original purchase.

## Parts List- (Please order by part number)

**RUNNING BOARD STRIPS:** Fit conventional model trucks 1936-1949, possibly others. Will fit any running board having mounting holes 4 3/4 inches apart.

<b>Parts No.</b>	<b>Price</b>
62. Complete set of strips: (2 with over the edge lips for trucks using 4 strips per side) (set of 8)...	\$420.06 set
82. Complete set of strips: (2 with over the edge lips for trucks using 5 strips per side) (set of 10)...	\$527.31 set
55. Plain strips: No over the edge lips (Express or larger trucks).....	\$55.41 ea.

**STRIPS WITH FLAT BOTTOMS:** Used by some restorers to protect paint on rear half of pickup runningboards, and for rebuilt running boards made with flat bottom rather than grooved as pre original. You will need to drill mounting holes.

<b>Parts No.</b>	<b>Price</b>
62F. (Set of 8) 6 plain and 2 with lips .....	\$ 464.75 set
62AE. Plain edge strips.....	\$60.78 ea.
62A. Plain flat strips.....	\$60.78 ea.

## 80 EXPRESSES (OLD STYLE) PICKUP

<b>Parts No.</b>	<b>Price</b>
13. Head light mounting pads (set of 4 pieces-2 ea. upper and lower) .....	\$65.25 set
29. Bumper bracket grommet (will fit older trucks).....	\$55.25 pr.
69. Axle snubbers.....	\$15.64 ea.
75. Motor stabilizer arm bushing (2 piece. 1 small, 1 large).....	\$21.45 set
84. Rear body mount, oval shaped, fits 80 with wood support and some early 201 (2 required).\$13.86 ea.	
86. Windshield rubber gasket, fits 1936-1938, 12 ft lengths. ....	\$143.00 ea.
104. Shock absorber arm linkage, (split arms) re-rubber your ends.....	\$47.29 end

## PARTS FOR 201 AND OTHER PICKUPS

<b>Parts No.</b>	<b>Price</b>
1. Gas filler pipe grommet.....	\$33.15 ea.
2. Front bumper bracket grommet (single bracket).....	\$57.20 pr.
3. Front bumper bracket grommet (double bracket).....	\$57.20 pr.
4. Rear spring shackle bushing (12 required).....	\$27.63 ea.
5. Front spring shackle bushing (12 required).....	\$21.145 ea.
6. Cab hole plug (gas filler).....	\$23.24 ea.
7. Rear of steel (Anthony) bed, bumper bracket hole plug for 3/4x7/8 slot...\$27.63 pr.	
8. Head light mounting pads.....	\$33.08 pr.

**PARTS FOR 201 AND OTHER PICKUPS, Continued...**

<b>Parts No.</b>	<b>Price</b>
8A. Head light mounting pads (1938-1939) only .....	\$28.60 pr.
9. Hood corners (set of 4).....	\$75.08 set
10. Steering column to fire-wall grommet.....	\$57.20 ea.
11. Hole plug for right-hand steering column, fire-wall.....	\$25.04 ea.
12. Dust seals, clutch-brake (2 required).....	\$37.54 pr.
56. Overload bumpers, mounts to rear frame (less brackets) (2 req'd) ..	\$53.63 ea.
69. Axle snubbers. ....	\$15.65 ea.
94. All fire-wall grommets (14 pc.).....	\$153.73 lot
29F. Rear bumper grommet, single bracket. ....	\$63.48 pr.
114B. Federal hood corners (set 4) must be drilled for rivet. ....	\$71.50 set

**PARTS FOR 210, 211 & 212**

1933-1935 may also fit other 2-series models from 1928-1937

<b>Parts No.</b>	<b>Price</b>
50. Headlight mounting pads (212 series).....	\$25.93 pr.
52. Front spring shackle bushing (crown end) (12 req'd).....	\$19.50 ea.
53. Front spring shackle bushing (flat end) (12 req'd) also fits 1931 model 216 & 211. ....	\$22.35 ea
54. Rear spring shackle bushing, also fits 304 (2 ea. front & rear lower) (8 req'd).....	\$26.81 ea.
55A. Rear spring shackle bushing (upper rear) (4 req'd). ....	\$31.29 ea.
83. Headlight mounting pads, fits 211AD, possibly others.....	\$33.08 pr.
87. Windshield gasket, fits 2-series models 1934-1936, 8 1/2ft lengths. ....	\$196.63 ea.
101. Motor mounts, fits 1933 model 210, must have your old core sleeves (set of 4). ....	\$67.04 set
102. Front cross member support bushing, 1933 model 210 (2 req'd).....	\$14.30 ea.
102A. Cab mount bush 222-620, 1950-56(3 req). ....	\$14.30 ea.
103. Rear window frame rubber, should fit 1934-1935 models 210-212, possibly others (4ft req'd). ....	\$52.74 ea.
69. Axle snubbers (212).....	\$17.88 ea.

**PARTS FOR 220 W/JXB HERCULES**

<b>Parts No.</b>	<b>Price</b>
81. Front motor mounts (1 set of 3 pieces req'd).....	\$57.20 set
82A. Rear motor mounts (2 sets of 2 pieces req'd)....	\$42.90 set

**PARTS FOR 306 (FARM TRUCKS)**

<b>Parts No.</b>	<b>Price</b>
2. Front bumper bracket grommet (single bracket). ..	\$57.20 pr.
3. Front bumper bracket grommet (double bracket)..	\$57.20 pr.
4. Rear spring shackle bushings (4 req'd). ....	\$27.72 ea.
5. Front spring shackle bushings (12 req'd). ....	\$21.45 ea.
6. Cab hole plug (gas filler). ....	\$23.24 ea.
6A. Gas tank filler grommet ( in cab). ....	\$27.63 ea.
8. Head light mounting pads.....	\$33.08 pr.
8A. Head light mounting pads (1938-1939) only .....	\$28.60 pr.
9. Hood corners (set of 4).....	\$75.08 set

**PARTS FOR 306 (FARM TRUCKS), Continued...**

<b>Parts No.</b>	<b>Price</b>
10. Steering column to fire-wall grommet.....	\$57.20 ea.
11. Hole plug for right-hand steering column, fire-wall.....	\$31.29 ea.
12. Dust seals, clutch-brake (2 req'd).....	\$37.54 pr.
69. Axle snubbers. ....	\$15.64 ea.
84. Rear body mount, oval shaped, fits early 306 with wood support (2 req'd).....	\$13.81 ea.
94. All fire-wall grommets (15 pcs).....	\$153.73 lot

**PARTS FOR LARGER TRUCKS**

<b>Parts No.</b>	<b>Price</b>
15. Brake-clutch, steering inset, brown. ....	\$173.06 ea.
16. Shifter boot, (409, 509, 614) straight.....	\$105.46 ea.
17. Hood corners for larger trucks(404, 509, 614) (set of 4). ....	\$71.50 set
18. head light mounting pads for larger trucks. ....	\$47.38 pr.
24. Hhock link and bushing/seal for (404,509,614) (set of 4) & (model 650, 1950).....	\$47.38 set
19. Shifter boot (404, 509,614) slanted.....	\$119.76 ea.
26. Front spring shackle bushings (12 req'd)also front 323. ....	\$34.86 ea.
26A. Rear spring shackle bushing, (4 req'd), also fit 910 front (12 req'd) and 969 military front...\$42.25 ea.	
27A. Gas filler grommets 2 1/4" filler pipe.....	\$27.63 ea.
27B. Gas filler grommets 2 1/2" filler pipe.....	\$27.63 ea.
28. Bumper bracket grommets for (404, 509, 614)using chrome bumper.....	\$55.25 pr.
42. Hood corners, fits only (900 series)(set of 4). ....	call for estimate
74. Spring shackle bushing, back-front, has square end fits some 509, possibly others....call for estimate	
90. Headlight mounting pads(fits 900 series)& (model 650, 1950). ....	\$37.38 pr.
91. Fender to hood rubber trim, fits 830 series possibly others (2 req'd).....	call for estimate
98. Headlight mounting pads for (1939-1940, 406).....	\$50.38 pr.
100. Front overload bumpers fit 900 series, must have your old cores (2 req'd).....	\$32.18 ea.
109. Inside cab mount bush (5 req'd) 921. ....	\$19.66 ea.
110. Outside cab mount bush (5 req'd) 921. ....	\$19.66 ea.
111. Headlight mounting pads, 522, 630, 662, 730, 921 (w/o stanchion). ....	\$71.50 pr.
114. Front emblem pad, fits 222-923. ....	\$16.09 ea.
115. Steering column insulator, fits 910R possibly others. ....	\$25.93 ea.

**PARTS FOR MOST ANY DIAMOND T**

<b>Parts No.</b>	<b>Price</b>
21. Mounting pads for King Bee lights on top of cab, (also 222-923).....	\$27.63 ea.
25. Fender bottom fits between front edge of fender & radiator frame (2 req'd per truck) fits most trucks.....	\$9.75 pr
30. Steering column insulator .....	\$8.13 pr.
31. Clutch and brake pedal pads (prior to 1950) on your old core only.....	\$38.44 pr.
32. Clutch and brake pedal pads (1950-1959) on your old core only (420-951). ....	\$38.44 pr.
33. Gas pedals, fit most every model, Made on your old core only .....	\$103.68 ea.
51. Body mount donut shaped cushion for back of cab (2 req'd).....	\$9.75 ea.
51A. Body mount donut shaped cushion for under the cowl (slice to shim both parts as necessary).....	\$9.75 ea.

<b>Parts No.</b>	<b>Price</b>
58. Diamond T stainless steel logo, unpolished ( 4"x7 1/8").	call for estimate
59. Diamond T stainless steel logo (same as above, polished one side).	call for estimate
114. Diamond T side emblem pad, fits 222-923.	\$16.09 ea.
66. Door check back stops (2 req'd).	\$9.59 ea.
70. King Bee mirror-rubber edging	\$17.88 ea.
71. Cab to cowl gasket, 5ft length.	\$75.08 ea.
72. Rear window gasket, 4ft length.	\$62.56 ea.
73. Windshield gasket, 12 1/2ft per truck for standard 14" high divider	\$196.63 ea.
73A. Windshield gasket, 14 ft per truck for some post-war 306, 404, 614 having 18" high divider	\$214.50 ea.
76. Door bumpers, 2 per door	\$15.20 ea.
85. Bumper, fits between inner fender and hood, fits most trucks (4 req'd).	\$15.20 ea.
92. Tool door bumpers	\$7.96 ea.
93. Cowl vent flap bumpers.	\$7.96 ea.
95. Bumper, door glass bottom, 2 per door	\$10.73 ea.
97. Window glass setting channel weather strip (56" enough for both doors).	\$50.84 ea.
99. Shock absorber linkage, (re-rubber your old ends).	\$42.01 end
107. Diamond T stainless steel logo, polished one side (5 3/4"x10").	call for estimate
108. Seat Pan Rubber (8ft req'd).	\$9.75 ft.

**MOTOR MOUNTS**

<b>Parts No.</b>	<b>Price</b>
34. (Set of 4) using your old cores	\$393.25 set
OR if you will burn off the old rubber and sand blast the parts.	\$294.94 set
EITHER WAY, condition of T Bolts are your responsibility.	
34A. T-Bolts, new	\$37.38 ea.
96. Rear motor mount model 323 possibly others, must have your old cores (2 req'd).	\$57.20 ea.

**PARTS FOR 702**

<b>Parts No.</b>	<b>Price</b>
77. Rubber discs, front cowl to frame mount (4 pcs).	\$24.05 ea.
78. Insulators, fits between wood frame rail in back of cab (2 req'd).	\$16.09 ea.
79. Dust seals, clutch and brakes.	\$12.51 pr.
80. Motor mounts (4 req'd).	\$57.20 ea.

**ACCESSORIES**

<b>Parts No.</b>	<b>Price</b>
23. Running board mats for trucks of the 30's (9x20") made from NOS pad	\$393.25 pr.
35. Hood clip protectors (for 4 pc hoods) pkg of 16.	\$14.30 pk.
43. Arm rest pads (specify color, BLACK-BROWN-GREEN).	\$112.61 pr.
60. Steel arm rest brackets--all trucks.	\$375.00 pr.
63. Running board mat for older trucks (9"x20") smooth no grooves w/logo	\$65.81 pr.
68. Teardrop parking lamp gaskets, 1936-1941.	\$16.99 ea.
89. Step mat, 8"x24" ribbed w/logo and edge lip, for trucks 1950 and later	\$536.25 pr.

**ACCESSORIES, Continued...**

<b>Parts No.</b>	<b>Price</b>
7A. Rear steel(Anthony)bed, bumper bracket hole plug for 1-1/4x 2-3/4 slot... ..	\$35.75 pr.
7B. Rear steel (Anthony)bed, bumper bracket hole plug for 15/16x2-11/16 slot....	\$35.75 pr.

**FLOOR MATS (Original BROWN) No Padding**

<b>Parts No.</b>	<b>Price</b>
36. (80, 201, 306) (includes gear shift ring and template for original punching).....	\$715.00ea.
37. (404,509,614) This mold has cracks which leaves lines in mat.....	\$509.44ea.
38. (704) and other larger trucks.....	\$518.38ea.
39. (212) you will also need clutch-brake inset, listed above in large truck section (part 15).....	\$518.38ea.
40. (210, 211) BLACK, includes clutch-brake grommet.....	\$536.25ea.
41. Pre 1950 COE (3 pcs).....	\$536.25ea.

**NOTE:** FLOOR MATS ARE CARVED IN WAX, THEN CAST OFF INTO A PLASTIC MOLD,SO THEY DO HAVE IMPERFECTIONS.

**Order Form Is On Next Page**

